



A-10	75 MC	W 1 RPM C.C.W.
MACH 3.2	HORIZ.	P 100 KW
90 M		N.F. 6



180-0197
Copy 141 rec'd


ARROW	75 MC	W 1 RPM C.C.W.
MACH 4	HORIZ.	P 100 KW
90 M		N.F. 6




A-10
MACH 3.2
90° M

75 MC
HORIZ.


W = 6 RPM C. C. W.
P = 100 KW
N. F. = 6




ARROW	75 MC	W=6 RPM C. C. W.
MACH 4	HORIZ.	P=100 KW
90 M		N. F. = 6



A-10	750 MC	W = 3 RPM C. C. W.
MACH 3.2	HORIZ.	P = 3 MW
90 M		N. F. = 6



ARROW	750 MC	W	3 RPM	C.C.W.
MACH 4	HORIZ.	P	3 MW	
90 M		N.F.	6	



G-2A

75 MC

W 1 RPM C.C.W.


MACH 0.9

HORIZ.


P 100 KW

70 M

N.F. 6



G-2A	75 MC	W 6 RPM C.C.W.
MACH 0.9	HORIZ.	P 100 KW
70 M		N.F. 6



Page Denied

Next 2 Page(s) In Document Denied

